

COPY

Ship's name "HSING YUNG"

Port

TAI

No.

64170

Last survey date 21.10.64

Class is subject to

For conditions of class see previous endorsement.

ACTION is DEFERRED for examination in drydock after grounding,  
also for equipment.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Equipment - supply and verification of a bower anchor  
and 135 fathoms of chain cable - see above. (See Yks. Surveyors  
letter dated 18.1.65).

Recommendation

SUBMITTED ACTION be DEFERRED for examination in  
drydock after grounding, subject to indented  
shell plate No.6 (p.s.f) in 5th strake below  
sheer and indented shell plate A.3 (s.s.a) being  
specially examined and dealt with as necessary  
next drydocking, also to spare bower anchor on  
board (supplied 10.64) being tested at  
the earliest opportunity, under other  
conditions.

SUBJECT  
WITHOUT.

IN S.R.L.

Drydocking (grounding).

IN S.R.L. APPENDIX.

Shell plate G.5 (s.s. from fwd) indented.

Indents in bottom shell plates in 'B' & 'D' strakes (p.s).

014083-014090-0001



© 2021

Lloyd's Register  
Foundation