

"Vic 10"

Jul. 5-1780  
Hewish 110,446  
Gy. 65-729

The boiler has been constructed under Special Survey and in accordance with the approved plan and M.O.W.T. Specification.

The machinery has not been constructed in accordance with the requirements of the Rules, but under the Society's supervision.

The machinery & boilers have been installed under the supervision of the Society's Surveyors and in accordance with the terms of the Specification.

It is submitted no further action is necessary.

The Hull Surveyors should be asked to confirm that no direct-bilge suction is fitted to the main circulating pump, as the arrangement was otherwise in previous vessels.

None

X class

20/10/62

Lloyd's Register  
Foundation