

DISCLAS
SECTION

Lon No. 126852 A

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of...

No. in Reg. Book 73087 on the Wood, Iron or Steel 55 "POLESIE"
Built at Selly By whom Cochrane + Sanson
GROSS 325 Owners Polish Government
UNDER DEK 288 Managers "Dulmar" P.P.D. Sp 2.0.0
NET 154

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
Cell DB or DBa feet: uE&B feet: f feet
total capacity tons. FPT tons: APT tons: MT feet tons.

Only alterations in the existing records of tanks should be inserted.
N.B.—All alterations in the existing records should be underlined.

Report, No. 2698 Port

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER for Special Survey, Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (including date of N.B., if any).
100M stem + LMC 10.51
Trawler 9.51 TSC 9.51
SS G.R. 5.46 (D)
SS Hfs 10.51

Medical Surveys, when held, must be reported in detail and ariatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and in detail the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the elements of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form state also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he has rendered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? if so, by whom?

OR EXAMINATION AS PER RULE FOR

DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
and Faired for Repaired,								
Repaired in place ..								

CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Ceiling	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Cement or Asphalt	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Rudder	Rudder	Scuppers	Boats
Steering gear and its connections	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Windlass	Windlass	Hatches	Condition, how ascertained (State if wedges removed.)
Have pumps been examined and found efficient?	Have pumps been examined and found efficient?	Planking	Equipment letter
Have Sluice Valves been examined and found efficient?	Have Sluice Valves been examined and found efficient?	Caulking	Anchors, No. of
Have Watertight Doors been examined and found efficient?	Have Watertight Doors been examined and found efficient?	Treenails	Cables (State if now ranged)
Have Ventilators and their Coamings been examined and found efficient?	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	length mean diamr (on board.)
Air and Sounding Pipes	Air and Sounding Pipes	Transoms, Pointers & Crutches	Rule length size
Doubling Plates under Sounding Pipes	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Chain Locker
		" " at other places	Hawsers & Warps
		Stringers, Clamps & Shelves	Standing and Running Rigging
		Salting (State if examined)	Sails

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1-38," or "to remain as classed and to have record of survey, 1-38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute TUES. 19 MAY 1953

Character Assigned wide own withdraw class
2 insert (...)

Surveyor to Lloyd's Register of Shipping
GENERAL COMMITTEE
21st May 1953
Classing Committee's decision confirmed.
014110-014123-0294

LLOYD'S REGISTER OF SHIPPING
DEAR SIR(S)
Boilers prescribed
Information of the
convenience

Is Certificate required? If so, to be sent to