

Received by Chief Ship Surveyor 18.8.17

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. Thomas Arkeniser Rpt. Hul No. 30104

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 37.12Depth "d" 12.16Framing: Table No. 3 page 10Description Single angle as approvedLongitudinal No. 5134Proportions $\frac{\text{Length}}{\text{Depth}} = 10.24$ Deck Sheerstrake 62 of an inch instead of 38 as required


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed $\text{I} 100 \text{ A.1. (Steel)}$ "Steam Trawler" as recommended

 $\text{I} 100 \text{ A.1. (Steel)}$ Steam Trawler.

1 DK.

BK $\frac{1}{2}$ " 4 BH. Cem. Lloyds Arch. & 78', F 19'

[Signature]
[Signature]
 18.8.17



Lloyd's Register
 Foundation