

Steamer "VIKING LIBERTY".

In August last the New Orleans Surveyor reported that the above ship, which had been under survey since February on account of bottom damage and stated engine misalignment due to grounding, had been sold and was being towed to Italy for scrap without any repairs being effected.

The Committee accordingly assigned the notation "To be broken up - class suspended".

Demolition of the ship was actually commenced at Santander at the end of August, and it is therefore submitted the vessel's class be omitted from the Register Book.

*L.R.D.*

8th November 1966.



© 2021

Lloyd's Register  
Foundation

014124 - 014134 - 0069

*Publ. Dept*  
*14/11/66*