

H. M. S. "MORGAN JONES".

LIST OF ENGINE ROOM OUTFIT.

Pair Smith's tongs.	3 Oil cans, assorted.
Catchet brace and stand.	2 Square brass lamps for engine room
Wheels, assorted.	1 Gauge glass lamp.
Old chisels, assorted.	1 Tallow tank.
Files, assorted and handles.	2 Hand lamps.
Packing drawer for each size of gland.	1 Tube lamp.
Packing sticks and 1 packing knife.	1 Drip tray and strainer, of brass.
Anvil and bench.	1 Trimming can and scissors.
Steel strake wedges.	1 Gallon measure and 1 half gallon measure.
Band hammers.	1 Tallow kettle, of copper.
Sledge or quarter hammer.	1 Set of eyebolts of different sizes to lift the different covers. (Fitted in rack on bulkhead).
Heavy flogging hammer.	1 Tin funnel.
Copper hammer.	1 Brass salinometer with case.
Lead hammer.	1 Can for do.
Lead hammer.	1 Thermometer of copper, of approved size.
Sealing hammers.	2 Iron ash buckets.
Dredging shovels.	2 Galvanized iron buckets.
Trimming shovels.	1 Set of spanners to fit each nut, $\frac{3}{8}$ inch to $1\frac{1}{4}$ inch.
Rakes.	2 Shifting spanners, small & large.
Shovels.	A rack to hold all spanners on bulkhead.
Long light rake for back ends.	1 Set of tubing tools for condenser.
Gricker.	1 Soldering iron.
Gricker blades.	1 Sheet of Muntz metal.
Tube brushes of brass wire.	2 Doz. assorted split pins.
Tube brush handle.	1 Spanner for safety valves.
Tube scraper and brush.	6 Lubricator glasses.
Necessary oil tanks, filled from deck, and pipes for same supply and fit.	12 Assorted studs & nuts.
Screwdriver.	6 Assorted brass studs & nuts.
Pair of tin shears.	1 Boilermakers' cramp.
Caulking chisels.	1 Set of cleaning tools for boiler.
Engine-room clock, brass.	1 Grindstone and trough, 18-inch.
Pair of plyers.	1 Stokehold drain tank.
25-ft. length of wash deck hose.	1 Set of blocks and falls.
Copper director.	1 Brass syringe.
Tube expander.	4 Tube stoppers and washers.
Set of taps and dies complete, $\frac{1}{8}$ inch to $1\frac{1}{4}$ inch.	6 "Woodite" rings for gauge glasses.
Wh cooling hose.	1 Expansion spanner.
Length of armoured suction hose for bilge suction box.	1 Bar of $\frac{3}{8}$ -inch, $\frac{1}{2}$ -inch, $\frac{7}{8}$ -inch, & 1-inch round iron studding.
Close-ended spanner for cylinder cover nuts.	3 Plates of iron, assorted (1-awt).
Manhole spanner.	
1 lb. of condenser cord.	
Sheets of tin.	

SEABOARD CLAR.

Main bearing bolts and nuts.	1 Complete set of firebars, including wing bars.
Top and bearing bolts & nuts.	1 Set of air pump valves.
Bottom end bearing bolts & nuts.	1 Main check valve lid.
Set of coupling bolts and nuts.	1 Monkey check valve lid.
2 Bolts and nuts, assorted.	

H. M. S. "MORGAN JONES".

SPARE GEAR (Contd.).

20 Brass ferrules for condenser
6 Gauge glasses.
1 Set feed pump valves and seats.
1 Set bilge pump valves and seats.
6 Piston bolts and nuts.
3 Boiler tubes.

6 Stay nuts.
1 Safety valve spring.
1 Set of feed donkey valves.
3 Condenser tubes.
3 Escape-valve springs.



© 2021

Lloyd's Register
Foundation