

F.E.

King King

Received by Chief Surveyor 16. 10. 99

Received from Chief Surveyor

EL'S NAME Lt. S. S. "Ponce"

Report OK No. 909

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>✓</i>	<i>✓</i>
Spar Sheerstrake . .	<i>✓</i>	<i>✓</i>
Description of Framing:— <i>Bulb angle</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100A1 ("Steel") *"Spar bulk"* as recommended.

∇ 100A1 ("Steel") *"Spar bulk"*

1 DR & Spar DR (Stt-WS) & web frames

W. B = Cell DBa 86' u EYB 60' f 124' 543t FPT 128t APT 68t

FK 6BH Cem. A & CP.

C.H. J.
16/10/99

It should be pointed out to the Surveyors that the equipment number being 30423 the letter per Table 22 is "U" and not "V" as stated in their report, and the equipment required by Table 22 should have been entered accordingly.

014198-014209-0421

© 2021

Lloyd's Register Foundation