

LLOYD'S REGISTER OF SHIPPING



Port..... D U B L I N .

Date..... 16. 12. 64.

This is to Certify *that I have surveyed part of the machinery*

of the TM. "GLANMIRE" 814 *gross tons* of CORK

for CSM and DAMAGE stated to have been caused by the starboard propeller striking an unknown object off Waterloo Lock, Liverpool on the 19.7.64, whilst lying afloat and in drydock at DUBLIN on the 3.12.64 and subsequent dates,

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following

survey records assigned CSM (with date) on completion, subject to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:—

~~Propellers, oil glands, sea fastenings, valves and cocks.~~

Main engines - Port No.3 and Starboard Nos.1 & 2 cylinders, pistons, valves and valve gears, connecting rods and their top and bottom end brasses, gudgeon pins and crank shaft pins.

Port Nos. 3 & 4 and Starboard Nos.1, 2 & 3 crank shaft journals and brasses.

Port main engine blower gearing.

Auxiliary diesel generator engine, port aft.

Ballast pump, starboard side forward.

Bilge pump, starboard side amidships.

Windlass.

H. H. Waggott

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."