

Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRS

Received London
16 SEP 1963

Ship's Name SS/MX Tug "HIMMA" Gross tons 274
 Is there a rpt. 9? yes Port Sydney NSW Rpt. No. 36226
 No. of visits one First date and Last date 3-9-63
 Interim Cert. issued & copy herewith? yes Damage rpt. issued & copy herewith? no Last rpt. (H.Q. only)
 Date of completing rpt. 10-9-63 Surveyed at, if different from Port above
 Surveyed afloat and/or in D.D. on slipway Last date of examination in D.D. 3-9-63
 Has a Load Line Survey been held? yes Freeboard Marks verified yes
 State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig) (PS)
 Survey fees £.12.0.0 Damage fee Expenses 8/0

S.A. fee

I have surveyed the above ship in accordance with the Rules for Docking survey, Annual load line, and examination of Rod- and-Chain steering gear.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Vessel examined on slipway and all found in good condition.

I recommend that this ship remain as classed with/without fresh record of dry docking 9/63.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate)

Date of Committee WEDNESDAY 16 OCT 1963

Minute

DS 9.63
MBS 8.63

Surveyor to Lloyd's Register of Shipping

(J. McCarlie)

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register
Foundation

014242-014252-0332

D

tion taken or recommended should be
scribed fully under "defects & repairs"
When any part has been subjected to
pressure test this should be stated.

e of the next Special Survey. Where re-
s have been effected or it is considered
that re-examination or repairs should be
made before that date the circumstances and

The condition of any item is to be described
as "good" only when it has been examined,
found or placed in good condition and is
considered to be acceptable until the due