

When taken or recommended should be
cribed fully under "defects & repairs"
when any part has been subjected to
pressure test this should be stated.

date of the next Special Survey. Where re-
pairs have been effected or it is considered
that re-examination or repairs should be
made before that date the circumstances and

is to be described
has been examined,
condition and is
able until the due

Date of
completing rpt. 19-9-62

Surveyed at, if different from Port above

Surveyed afloat
and/or in D.D. both
Has a Load Line
Survey been held? yes (Annual)

Last date of examination in D.D. 29-8-62

Freeboard Marks verified yes

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig) PS (dryca

Survey fees £.12.0.0

Damage fee -

Expenses 5/0

S.A. fee -

I have surveyed the above ship in accordance with the Rules for Docking and Ann
Loadline survey.

The items now surveyed are detailed on this report. All were found or placed in good conditi
otherwise stated.



© 2021

Lloyd's Register
Foundation