

S/S "Robin"

Ips. Low. 92280

It is submitted that the Ipswich Surveyor should be requested to state whether the thru shaft is 5.75 inches diameter under the collar as by the Rules it should be not less than 5.9 inches.

Shaft 6" diam see Ltr 15/2/28

Lr Ips. 14/2/28.

JWD.

13/2/28.

Lloyd's Register
Foundation