

COPY
LLOYD'S REGISTER OF SHIPPING



Port G I J O N

6th March, 1968

This is to Certify that I have surveyed part of the machinery of the **M.S. CAMPECHE, 6382** Gross tons of Tarragona for **Drydocking and auxiliary boiler survey**

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned. **ABS 3,68** subject to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:—

Propellers and all outside fastenings.
Port and starboard auxiliary boilers internally and externally with mountings and safety valves and the safety valves of both boilers adjusted under steam.
Oil burning system and remote controls.

NOTE. The safety valves of both boilers have been adjusted such that the working pressure shall not exceed 8kg/cm².

R.M. Hobson.
Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey.
CSM Continuous Survey of Machinery.
DBS Donkey Boiler Survey.
ES Engine Special Survey.
MBS Main Boiler Survey.
OF Fitted for oil fuel (date) FP above 150° F.

SGS Steam Generator Survey.
SPS Steampipe Survey.
TS Tailshaft Survey.
TS(CL) Tailshaft Survey—Continuous Liner.
TSN Tailshaft renewed.
TS(OG) Tailshaft Survey—Oil Gland.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society.