

Lord Kelvin

The Surveyors attention should be drawn to Circular No 12824 and they should be requested to forward full particulars of the length & capacity of all double bottom tanks, including the dry tank under the Boilers if this space has been made watertight & tested as required by the Rules.

They should also be requested to forward the length & capacity of the deep ballast tanks at the sides of the tunnels.

M.
3-4-16



© 2021

Lloyd's Register
Foundation

014287-014299-0331