

sp. Lord Kelvin.

New. Rpt. 68618.

It is submitted that the Newcastle Surveyors should be requested to state the dates of the examination of the completion of fitting the sea connections, stern tube, screw shaft & propeller, omitted from their report.

J.W.D.

4/4/16.

© 2021

Lloyd's Register
Foundation

014287-014299-0334

If stiffened with rings

Distance between rings

Working pressure of

Working pressure of end plates

Area of safety valves to superheater

Are they fitted