

4E

19 MAY 1953

d by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

S NAME "CITY OF CANTERBURY" REPORT Drb. No. 6141.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

MBS due 6.52 partly held 2.52 not advanced.

Wear and Tear.

The flange attachment to the IP cylinder cover was cracked, permanent repairs have now been carried out.

IT IS SUBMITTED that this vessel is eligible to remain as classed.



© 2021

24  
15.5.53.

Lloyd's Register  
Foundation

014320 - 014311 - 2294