

Special Investigation by Engineer Research Department

1

No. in Reg. Book ⁶⁹⁷⁶⁷

Vessel's Name 'MELIKA'

Case No. E.R.D. 1234

At the request of the Owners, Afran Transport Co.,
an investigation is to be carried out into the cause of
failure of the L.P. turbine rotor on the above vessel.



© 2021

Lloyd's Register
Foundation

(Signed)

Surveyor to Lloyd's Register.

8268

-0143

ight tail pipes to the bilges. Yes ✓

014335-014348-0269

FEB
Nov 1. 11
h