

Ship's Name SS/MX "KEYSHEY"

Gross tons 1796

Is there a rpt. 9? Yes

Port MONTREAL

Rpt. No. 15746

No. of visits 1

First date and

Last date 30th Sept./63

Interim Cert. issued
& copy herewith?Damage rpt. issued
& copy herewith? -

Last rpt. (H.Q. only) -

Date of
completing rpt. 26/11/63

Surveyed at, if different from Port above Kingston

Surveyed afloat
and/or in D.D. Afloat

Last date of examination in D.D. -

Has a Load Line
Survey been held? Yes

Freeboard Marks verified -

State which additional Rpt. 8 is attached: (Cont); (DR); (EQ); (Rig)

Survey fees \$40.00

Damage fee

Expenses \$30.00

MTL-2155 16/12/63

S.A. fee

I/we have surveyed the above ship in accordance with the Rules for Lake

Annual Survey

Examined & Condition

Examined & Condition

Holds, incl. blkhd.,
inner btm. plating, etc

Good

Pumps & pumping arrgts.
outside mchy. space

Good

Bilges & ceiling

Good

Steering arrgts. incl. gear

Good

Tween decks

Good

W.T. doors & sluice valves

Good

Deck &
deck erections

Good

*Ventilators

Good

Machinery space

Good

*Hatchways

Good

Under E. & B.

Good

*Casings & companionways

Good

Masts, rigging &
outfit

Good

*Superstructures

Good

Windlass &
hawse pipes

Good

Guard rails & freeing ports

Good

*Air & sounding
pipes

Good

Overboard discharges, ash
chutes & other shell openings

Good

Examined &
conditionTested &
conditionExamined &
conditionTested &
condition

Peaks Good

Tanks { Cargo tanks
Cofferdams
Pump rooms

Side tanks in hold -

Deep tanks -

Has a grain survey
been held? N/A

Has a damage survey been held? No

The items now surveyed are detailed on this report. All were found or placed in good order unless otherwise stated.
I/we recommend that this ship remain as classed with fresh record of Annual Survey. 9,63

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee TUESDAY 14 JAN 1964

Minute As now

AS 9.63

MBS 9.63

Surveyor(s) to Lloyd's Register of Shipping

C. BUCHANAN

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

014364-014371-0011

Lloyd's Register
Foundation

ion taken or recommended should be
described fully under "defects & repairs".
When any part has been subjected to
pressure test this should be stated.

date of the next Special Survey. Where
repairs have been effected or it is considered
that re-examination or repairs should be
made before that date the circumstances and

The condition of any item is to be described
as "good" only when it has been examined,
found or placed in good condition and is
considered to be acceptable until the due