

COPY

PROVINCIA DE MOCAMBIQUE

DIRECCAO DOS SERVICOS DOS PORTOS, CHAMINHOS DE FERRO
E TRANSPORTES.

Lourenco Marques 11 de Marco; 1954.

Senior Surveyor,
Lloyd's Register of Shipping,
Cato House,
Smith Street,
DURBAN.

Dear Sir,

With reference to your letter of the 9th February last which I acknowledge with thanks, below please find the information requested :

- a) No. modifications or reparations have as yet been made on the Engines Survey due to lack of opportunity, although it has been thought of, but the reason why we have not felt so much the need of this modification is because we have two agents at the machines, one at each engine as requested by the Captaincy.
- b) As we do not have a dique (dock) on this Division it is impossible to send the vessel to a drydock. The improvements of the flank and bottom are made by running the vessel on to the beach, approximately every six months, the last time having taken place from 26th September to the 8th October, 1953, at the port of Lumbo.

Yours faithfully,

DIRECTOR GENERAL.

Pereira Leite.



© 2021

Lloyd's Register
Foundation

014364 - 014371 - 0271