

10. JUN. 1966

Ship's Name SS/MS "ARCTIC HUNTER"

LR. 502239

Port of Registry Hull.

Gross tons 579

Port HULL.

Date of build 3.1946. Is there a Rpt. 9? Yes.

Rpt. No. 71526.

No. of visits One.

First date and

Last date 26/5/66.

Interim Cert. issued & copy herewith? Yes.

Damage rpt. issued & copy herewith? No.

Last rpt. (H.Q. only) Hull 71326

Date of completing rpt. 7/6/66.

Surveyed at, if different from Port above

Surveyed afloat and/or in D.D. Drydock.

Last date of examination in D.D. 26/5/66.

Has a Load Line Survey been held? None.

Summer freeboard as verified -

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees

Damage fee

Expenses

S.A. fee

I have surveyed the above-named ship in accordance with the Rules for DOCKING & ANNUAL SURVEYS.

A number of minor wear and tear repairs effected.

S.R.L. APPENDIX No. 17:-

"Sternframe at outer E.W. 8,61 and previously".
Now examined and found to remain efficient.

RECORD OF INSPECTION OF SAFETY EQUIPMENT.

Issued by B.O.T. Hull 7/6/66.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed with/without fresh record of dry docking 5,66.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

WEDNESDAY 29 JUN 1966

DS. 5.66

MBS 5.66

TS. 5.66

Surveyor to Lloyd's Register of Shipping

FOR CHAIRMAN
CLASSN. CTTEE.

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

014480-014491-0324

Lloyd's Register
Foundation

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name SS/MS "ARCTIC HUNTER"

Port HULL.

S.S. (C) Due 10,69

Rpt. No. 71526

In dry dock from 26/5/66.

In dry dock to 27/5/66.

<u>Examined & condition</u>		<u>Examined & condition</u>	
Shell plating	Good.	* Air & sounding pipes	Above deck, good.
Sternframe	Good.	Doublers under „ „	Not examined.
Rudder	Good.	Steering arrangements (main)	Good.
Was rudder lifted?	No.	„ „ (aux)	Good.
Plating, etc. in way of shell openings	Good.	Windlass	Good.
Side scuttles & deadlights	-	Masts & standing rigging	Good. From deck.
Overbd. scuppers & discharges	-	Hand pumps & suction	Not examined.
F.P. spaces	Not examined.	W.T. doors	None.
Chain locker	Not examined.	Bulwarks, freeing ports, etc.	Good.
A.P. spaces	Not examined.		
Engine space	Not examined.		
Boiler space	Not examined.		
Under E. & B.	Not examined.		
Coal bunker	Not examined.		
Tunnel & well	Not examined.		
Cement, asphalt, etc., on btm. shell	Not examined.		
Weather decks	Good.		
* Casings	Good.		
* Deckhouses	Good.		
* Superstructures	Good.		
* Skylights	Good.		
* Companionways	Good.		
* Hatchways	Good.		
* Ventilators	Good.		
Other items:	-		

EQUIPMENT:

	Equipment letter	x
	Fee ltr., if diff. from eqpt. ltr.	j
	Anchors: No. on board	2B 1K
Cables {	State if ranged	No.
	Length on board	Stated complete.
	Mean dias. range from	- to
	Rule length	- Dia.
	Mooring ropes	Sufficient.

* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2021

Mr. S. Blain
 Surveyor to Lloyd's Register of Shipping
 Foundation

014480-014491-0324²/₂