

to Chief Surveyors

Received from Chief Surveyors

SHIP'S NAME *Stl. T.S. " MONTEREY "* Report *S. L.* No. *6695*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Particulars of Survey *1<sup>st</sup> Entry* When due *✓*

*100 A1 (Steel) "with Freeboard."*

*4 D<sup>ks</sup> (Stl), 5<sup>th</sup> D<sup>k</sup> (Stl) in forward hold, & Web frames*

*bell DB. 514' 3308t, Tanks in way of tunnels 1081t, FPT 178t, APT 161t.*

*FK, 11 BH, asp.*

*B 410' F 60'*

*Date of build 4.32*

*See endorsement*



*Hand.*  
© 2021  
*28.6.32.*

Lloyd's Register  
Foundation

*Had repairs reqd before Classing Cert can be issued*

*014513-014530-0043*

*9775222 021 120*