

COPY.

Lloyd's Register of Shipping



Port Galveston, Texas

..... August 20, 1948

Cert. No. 158, 159 & 160

This is to Certify that

..... JAMES FINDLAY

the undersigned Surveyor to this Society did at the request of

the owners representative attended at the works of Todd Shipyards Corporation, Galveston, Texas on the 14th July, 1948 and the 4th and 5th August, 1948 for the purpose of examining screw shafts for the M/V "JOSURE".

The rough machined bar had marks -

C.F.Co.
HT - 8363
SER - 2689
LLOYD'S
5899
3-7-48

C.F.Co.
HT - 8363
SER - 2690
LLOYD'S
5900
3-7-48

C.F.Co.
HT - 8363
SER - 2691
LLOYD'S
5901
3-7-48

The screw shafts were examined by the undersigned after machining, so far as could be seen, sound and free from defects.

For identification purposes the shafts were marked as follows:

C.F.Co.
HT - 8363
SER - 2689
LLOYD'S
5899
3-7-48
LLOYD'S No. 158
J.F. 14-7-48

C.F.Co.
HT - 8363
SER - 2690
LLOYD'S
5900
3-7-48
LLOYD'S No. 159
J.F. 5-8-48

C.F.Co.
HT - 8363
SER - 2691
LLOYD'S
5901
3-7-48
LLOYD'S No. 160
J.F. 5-8-48

Fee \$55.00

James Findlay
Surveyor to Lloyd's Register of Shipping

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly carried out, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

PRINTED
IN
U.K.

© 2021

Foundation

014513-014530-0453