

EA

COPY

Ship's name "MONTE AYALA"Port

BBO

No. 13484Last survey date 20.4.63.Class is subject to

NONE.

S.R.L. Appendix (as before or none)Nature of present survey (afloat and in drydock)

Docking: Deferred repairs to damage - cause not stated.  
Temporary wear and tear repairs.

Recommendation SUBMITTED record of DS 4,63 be assigned, subject to  
indented shell plates No.4 in 4th below sheer and No.  
and 5th below sheer (p & s) and wasted shell plates No.1 in  
7th below sheer (p & s) being specially examined and  
dealt with as necessary next drydocking.

DS 4,63 Subject.



© 2021

Lloyd's Register  
Foundation

End. S.1

014556 - 014565 - 0237

must be stated above and on the interim certificate.)

Signed: Ian H. White  
Surveyor to Lloyd's Register of Shipping

SRL