

COPY

LLOYD'S REGISTER OF SHIPPING



5584

SS/MS Port ABIKO Iokohama
 This Certificate
 Accompanies YOKOHAMA
 No. 5-508 7th November 1964
 REPORT No. 19-11-64

This is to Certify that ~~I~~^{we} have surveyed part of the machinery of the S.S. "ABIKO" 7086 Gross tons of Hong Kong for Docking Survey, MBS, Part ES and General Examination for postponement of Special Survey whilst the ship lay in drydock and afloat at Hakodate on the 3rd November 1964 and subsequently

and that all ~~my~~^{our} recommendations have been carried out to ~~my~~^{our} satisfaction. ~~I~~^{We} ~~am~~^{are} reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned MBS 11/64 (now) and ES (with date) on completion, subject to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:—

Propeller.
Sea connections & fastenings.

For MBS 11/64

Port, Starboard & Centre boiler throughout and their safety valves adjusted under steam.
O.F. burning system and remote controls examined as per rules.


For Part ES

Boiler F.O. burning pumps (inboard & outboard)
Boiler F.O. heaters (" " ")

For General Examination for postponement of SS

Machinery examined under working conditions.
Electric equipment - megger tested.
Pumping arrangement - examined & tested.

For K. Ikehata & self


S. TAKENAKA
Surveyor to Lloyd's Register of Shipping

ABS Auxiliary Boiler Survey
CSM Continuous Survey of Machinery
DBS Donkey Boiler Survey
ES Engine Special Survey

MBS Main Boiler Survey
OF Fitted for oil fuel (date) FP above 150° F.
SGS Steam Generator Survey
SPS Steampipe Survey

KEY TO ABBREVIATIONS

TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."