

Leatham D. Smith S.B.Co. Sturgeon Bay, Wis. U.S.A.

Similar to 'WILLIAM BURSLEY'

Received by Chief Ship Surveyor

GB

Received from Chief Ship Surveyor

ESSELS NAME s.s. "WILLIAM HOMAN"

REPORT

Gms.

No. 23932

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This American Type N.3-S.A. vessel was built in 1943, and previously classed with the British Corporation.

Classification with this Society is desired.

The scantlings and arrangements have been found suitable for the class 100A1.

The GRIMSBY Surveyors in a First Entry Report and Rpt.8, report 9.49, the vessel examined in dry dock and afloat. The scantlings and arrangements verified, and the requirements of a Periodical Special Survey complied with.

On account of damage due to the explosion of a mine, repairs and renewals effected to a number of shell plates, frames, floors, and other items.

The equipment of anchors and chain cables on board complies with the Rules, and has been tested partly by the American Bureau of Shipping and this Society, it is submitted the figure '1' be assigned, the Notation 'Lloyd's A & CP' being omitted.

It is further submitted the vessel is eligible to be classed 100A1 with record of docking 9.49, and Notation of 'ss. 8.49'.

100A1

8.49 Imm.

ss. Imm. 9.49

Classed 9.49.

1 Dk "Elec. welded"

Cell DB 209' 489t, FRTs 74t, APT 41t.

P 22' B 70' F 26'

ESD

"q"

The Certificate of Classification to be endorsed 'Cargo Batten-not' and the same notation to be printed in the Register Book.

INSERT IN S.R.L.

(Bottom under boilers to be examined internally ^{annually} (cement omitted)).

23.11.49



© 2021

Lloyd's Register
Foundation

014574-014581-0287