

to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME PLATANO REPORT Mob. No. 2532

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

re of Survey Docking. When due

This vessel is classed BS* (with Freeboard).

Mr. Bennett in endorsement dated 6.3.51. states

"This vessel was under survey at Mobile on the 12th of January, 1951 but before the survey was completed on the 9th of February, 1951, a letter, dated January 30th, 1951 was received from Agencia Maritima Hondurena, S.A., intimating that, on the instructions from the Owners, Empresa Hondurena de Vapores, S.A., this vessel was being withdrawn from the Society's classification as from the 9th of February, 1951."

and submits

"the record of 'BS* class withdrawn' be made in the Register Book in the case of this vessel."

IT IS ACCORDINGLY SUBMITTED the vessel's class be withdrawn from the Register Book and "BS* class withdrawn" be inserted in lieu, indicating withdrawal at the Owners' request.

Withdraw Class

INSERT IN R.B:

✓ BS* class withdrawn

ABM.
24.3.51
L.A.M.



© 2021

Lloyd's Register Foundation

014642-014653-0036