

*Received from Chief Surveyors*

RECEIVED FROM CHIEF SURVEYORS

CHIEF SURVEYORS

REEL'S NAME *Steel Screw Toppers Barge No 428* Report *GL* No. *34609*

**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - *Extract from Sub-Committee's Report, 24/5/92.*)

re of Survey 1<sup>st</sup> July When due

♣ 100 A-1 (steel) "Hopper Barge"  
1 DX (steel)

WB = FPT 456. Wing Canks 54' 1786.

F.K. 434. Asp 2 Lycop. a + r.

J.M.  
25. 11. 14

The Surveyors should be requested to state whether the record of Aspi should be made in the Register Book in this case.

see glo memo  
Oct. 8/17/18.

© 2021

<sup>23</sup>  
~~Lloyd's Register~~  
Foundation

014738-014750-0063

[illegible]