

8th May, 1937.

n.1,87.

BOARD REPORT on the


JOSEPH PHILIP

is submitted the Hull Surveyor is requested to state if there are now
 sidelights to the crew's space forward, and if the 4-15" cast iron
 at bunker scuttles have been closed up as there are shown on the
 C.11.
 final report.

H.

B.B. 11.5.37.

11/5.



© 2021

Lloyd's Register
Foundation

014738-014760-0073