

5 E
6- MAR 1951

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

ES NAME

"HOEVELD"

REPORT

Drb.

5584

C.Tn.

No 4229

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

Survey

DAMAGE & WEAR AND TEAR.

Docking.

Main and auxiliary machinery generally examined for Annual Survey.
One port boiler plain tube renewed and leakage in starboard boiler dealt with.

Blr.S due 2.51 not held.

It is submitted the vessel is eligible to remain as classed, with
~~record of survey~~ as recommended.



© 2021

Lloyd's Register
Foundation

Thru
674
2.3.51.

014761-014762-0101