

4 E

By Chief Engineer Surveyor

Received from Chief Engineer Surveyor

E2 MAY 1949

EL'S NAME

"VIC 74"

REPORT

Cbo.

No. 2225

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement is to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

~~REPAIRS TO ENGINES AND BOILERS DONE TO VESSEL THROUGH~~

The boiler of this vessel was constructed under Special Survey in 1945.. The machinery and boiler were installed under the supervision of the Society's Surveyor and in accordance with the M.O.W.T. specification; and First Entry reports were forwarded.

The Colombo Surveyor now reports having carried out a boiler survey, an examination of the screw shaft and a General Examination to enable the vessel to proceed to Bombay, where it is intended to hold a Special Survey with a view to Classification.

IT IS SUBMITTED action be deferred pending a report from the Bombay Surveyors.

As the vessel is intended for restricted service the Bombay Surveyors should be requested to discuss with the Owners the amount of spare gear considered essential.

[Signature]
30.4.49.



© 2021

Lloyd's Register
Foundation