

11 OCT 1941

ed by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SEL'S NAME CHIEN SHE REPORT Shi. 4916
No.....

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class of this Chinese-owned ship was omitted from the reprint of the 1944-45 Register Book.

The SHANGHAI Surveyors report (7.47) the ship examined in dry dock, ~~bottom coated~~, the requirements of a PERIODICAL SPECIAL SURVEY (C) ~~for reclassification~~ complied with, and on account of wear and tear, a few minor repairs effected.

On account of 4 damages due to various causes repairs effected to a few shell plates, frames, and other items, and permanent repairs recommended to slightly set in shell plates in 2nd, 3rd & 4th strakes below sheer etc. (s.s) at the first convenient opportunity.

It is submitted this dredger is worthy to have her class reinstated in the Register Book, with particulars as formerly, with record of docking survey 12.46, and to have the notation of 'S.S. Shi. - 7.47', subject to permanent repairs to slightly set in shell plating in 2nd, 3rd & 4th strakes below sheer etc. (s.s) at the first convenient opportunity.

Reinstate Class:

LOCAL "Hopper Dredger"

12.46 Shi.) subject
'S.S. Shi. - 7.47')

Reclassified 7.47



© 2021

Lloyd's Register
Foundation