

4 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "CHIEN SHE"

Rpt.

Shi. No. 4916

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

The class of this Chinese owned vessel was omitted from the 1944-45 copy of the Register Book.

A complete LMC and screw shaft surveys have now been held.

Minor repairs effected to main engines and some auxiliary machinery parts renewed and some repaired.


Port screw shaft previously welded, now renewed, also stern bush "A" bracket renewed.

Some boiler tubes renewed.

IT IS SUBMITTED that this vessel is eligible for the particulars of class to be re-instated in the Register Book and the Record @ LMC 7.47,

Port SN 10.46,

Star. S 10.46.



© 2021

Lloyd's Register
Foundation

9.10.47.

2110-966410-111110