





DAMAGE CON<sup>TD</sup>

a Diesel engine. The owners desire that this shaft  
be accepted by this Society. Brinell tests were taken  
when the following result was obtained  
148 Hardness 32.56 tons taken at three points  
on the shaft.

The acceptance of this shaft is submitted  
for the favourable consideration of the Committee.

M. H.



© 2021

Lloyd's Register  
Foundation