

13. JUN. 1966

Ship's Name ~~SS/MS~~ Contella LR 540273  
Gross tons 1695 Port of Registry Helsingfors Port Åbo  
Date of build 8.34 Is there a Rpt. 9? No Rpt. No. 1697  
No. of visits 3 First date 18/5/66 Last date 21.6.66  
Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) ABO 1698  
Date of completing rpt. Surveyed at, if different from Port above -  
Surveyed afloat and/or in D.D. Both Last date of examination in D.D. 18.5.66  
Has a Load Line Survey been held? No Summer freeboard as verified -

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees  
200. -

Damage fee

Expenses 8. -

S.A. fee 45. -

I have surveyed the above-named ship in accordance with the Rules for examining the bottom  
Rudder, Sternframe and propeller all in order except for W & T below.

Wear and Tear

Found Rudder upper pintle slack.

Now dealt with and nut renewed.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.  
I recommend, therefore, that this ship remain as classed with/without fresh record of docking survey

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

THURSDAY 30 JUN 1966

DS 5.66

NOTE RB.

note DS  
Write ABO (m)

Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

C.B.S.

TRO

DEPT.

SRL

POSTING

HEADER

CERT

FOR CHAIRMAN  
CLASSN. CTTEE.

014771-014776-0305