

COPY.

Lloyd's Register of Shipping,

united with THE BRITISH CORPORATION REGISTER.



Port of Rotterdam

16th March, 1956.

BELONGS TO
ROTTERDAM REPORT No. 41198

This is to Certify that

H. Schippers,

the undersigned Surveyor to this Society did at the request of

Messrs. Cia. Shell de Venezuela attend at the yard of Messrs. N.V. Werf Gusto v/h A.F. Smulders at Schiedam for the purpose of examining and testing the pumping arrangement of the Drilling Barge "G.P. 7", 1434,21 tons gross of Maracaibo, built under Yard No. 100 on the 20th January, 1956.

The machinery of the vessel is not classed with this Society but examination has been based on the requirements of the Society's Rules for Pumping and Piping with the exception of the pumps which have not been built under survey of the Surveyors of this Society, but are supplied by the Owners.

No survey has been carried out of the installation as a whole based on the Owners' specification, nor has the drilling equipment been examined for compliance either with the specification or the Society's Rules.

The pumping arrangements together with the air and sounding pipes has been constructed in accordance with approved plan No. 222633 and the amendments, and secretary's letter while the materials used are of good quality and the workmanship found good.

On completion the bilge and ballast lines were tested by a head of water as required and the pumping arrangement examined under working conditions on all compartments with satisfactory results.

For Mr H.A. Schippers:

G. Williams


SURVEYOR TO LLOYD'S REGISTER.

Fee.....Fls. 200.-
Trav.Exp. " 4.-
applied for 13.4.56.

W.H.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, Surveyors, or other Officers or Agents of the Society."



© 2021

Lloyd's Register
Foundation

01477-014793-0123