

Turbo Electric Machinery.

The first entry reports for this Case as being forwarded for your information and noting regarding the electrical reports. Attention is drawn to the removal of 15% of the Superheater elements owing to excessive Superheat temperature.

Regarding the NWC. report 4.d. the shaft horse power given as 11,000 and in this connection reference to Cey. letter 15.2.45 to Sld Surveyors might be made. The NWC. Surveyors do not specifically refer in their report regarding the results of their investigation. Should the results at 13,000 S.H.P. have proven satisfactory on the motor. I am not quite clear if it was intended that this figure should be regarded as a permanency.

Should you consider further information be necessary regarding the trial results other than reflected in the reports would you kindly take up the point with Hwe.

Ham

24. 6. 45

Please return Correspondence etc to Wok  
after perusal.

C.E.S. London.

2 N.H.P. which was calculated on 13000, is 2579. |||

© 2021

Lloyd's Register  
Foundation  
016784-01673-0030

016784-014763-0030