



LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London E.C.3

Telephone: ROYal 9166
Telex No.: 24305

Please address further
communications on this subject
to THE SECRETARY
and quote the following
reference

R

Dear Sir(s),

Records indicate that screwshaft failures in ships of 'Liberty' or 'Near - Liberty' type continue to occur at a higher rate than in other ships, and in view of this the Committee consider that the interval between surveys should not exceed the three years prescribed by the Rules.

Consideration will, however, be given to the circumstances of any special case if Owners can show that they have taken positive steps in an effort to reduce the risk of failure, and that the precautions recommended by the Society have been carried out.

The Screwshaft Survey of your steamer
"SUDBURY HILL" will become due in
November and, as this is one of the type
of ships referred to above, I shall be glad to learn
that you will comply with this inspection at about
the due date.

Yours faithfully,

R. H. Cook

Classification Manager,

*The Committee Shipping Ltd.
St. Clare House,
30-33 Abchurch Lane,
London E.C.4*

© 2021

Lloyd's Register
Foundation

014 806-014 814-0132