


COPY

LLOYD'S REGISTER OF SHIPPING



Port Sydney, N.S.W.

Date 22nd June, 1965

This is to Certify that I have surveyed part of the machinery of the S.S. "SUDBURY HILL" 7,140 gross tons of London for Completion of Main Boiler Survey, and Examination of Windlass and Main Condenser Water Box Repairs.

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned M.B.S. 4/65 now, and C.S.M. (with date) when the survey has been completed subject to the Windlass Starboard Side. Outboard main bracket being renewed and the starboard gypsy being specially examined and dealt with as found necessary, by 9/65 and to the main condenser water box being specially examined and dealt with as found necessary by 9/65g and to any other condition of class being dealt with as previously recommended.

Parts now examined:—

For Completion of M.B.S.

Port Main Boiler Air Heater
Centre and Starboard Main Boiler in their entirety
Port, Centre and Starboard Main Boilers Oil Burning Systems and remote controls examined.
Port, Starboard and Centre Main Boiler Safety valves adjusted at 220 P.S.I.


Surveyor to Lloyd's Register of Shipping
(J.H. JAMIESON)

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey	MBS Main Boiler Survey	TS Tallshaft Survey
CSM Continuous Survey of Machinery OF	Fitted for oil fuel (date) 150' F	TS(CL) Tallshaft Survey—Continuous Liner
DBS Donkey Boiler Survey	SGS Steam Generator Survey	TSN Tallshaft renewed
ES Engine Special Survey	SPS Steampipe Survey	TS(OG) Tallshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021

Lloyd's Register Foundation

014 206 014 314-0186