

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex  
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

8th February, 1965.

C  
DNS/CB


Dear Sirs,

Steamship "SUDBURY HILL"

The Reports of the survey carried out by the Society's Alexandria Surveyors between the 10th November and 26th December have now received the consideration of the Committee.

As a result of this inspection the Committee have continued the vessel's class subject to the following items receiving attention by the times stated.

1. Defective length of chain cable (starboard side) still on board being repaired and retested or renewed at the earliest opportunity.
2. Guard rails abreast Nos.1, 2 and 5 hatchways (starboard side) and Nos.4 and 5 hatchways (port side) and to No.2 D.B. air pipe (port and starboard) being specially examined and dealt with as necessary by the end of this month.
3. Starboard hawse pipe (repaired 12.64) and side shell plating etc., in way of port hawse pipe being specially examined and dealt with as necessary by March, 1965.
4. Windlass starboard side outboard main bracket being renewed and the starboard gypsy being specially examined and dealt with as necessary by the end of March, 1965.



© 2021

Lloyd's Register  
Contd.  
Foundation

014 306 014 814-02051



- 2 -

I shall be glad to learn what arrangements  
you propose to make for the above matters to  
receive attention,

Yours faithfully,

pro Clerk to the  
Classification Committee

The Counties Ship Management Co Ltd ,  
St Clare House,  
30-33, Minories,  
LONDON, E.C.3.



© 2021

Lloyd's Register  
Foundation

0210522