

4 FFR 1965

Ship's name ⁴ SS SADBURY HILL

Port ALEXANDRIA No. 5752

Class is subject to

Last survey date

26.12.64

① Windlass stowd. cable lifts (crack at dog) being examined & dealt with by 2.65 (3 months).

Surveyor reports subject item now examined.

Windlass stowd. frame temporarily repaired in way of crack, alleged to have been sustained during heavy weather.

Surveyor recommends windlass stowd. side outboard main bracket to be renewed & the stowd.

gypsy to be specially examined & dealt with as necessary by March 1965 (2 months).

It is submitted that this vessel is eligible to remain

as CLASSED.

regarding subject item ① & subject as recommended.