

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

31st December, 1964.

C.
DHGK/BN

Dear Sir,

CLASSING LETTER

4859 "SUDBURY HILL". As recommended, except that class has been continued subject to the length of chain cable (supplied Gibraltar 11.64) being verified with Certificates, to a bower anchor and 7 lengths of chain cable being supplied at the earliest opportunity also to the remaining chain cable (starboard side) and hawse pipe (starboard side) and windlass starboard cable lifter being specially examined and dealt with as necessary by February 1965, and to rudder bottom bush being specially examined and dealt with as necessary at the next drydocking as previously recommended.

Yours faithfully,

pro Clerk to the
Classification Committee.

R. Clarke Esq.,
GIBRALTAR



© 2021

Lloyd's Register
Foundation

04806-24814-0209