

Ship's name <sup>83.</sup> "SUDBURY HILL"

Port

Gibraltar

Rpt 8

No. 4859

Class is subject to

None.

Last survey date

1/11/64

Repairs.

Handles starboard bow band renewed (broken).  
Starb. cable lifter cracked at dog and the surveyor  
recommends that the wireless starboard cable lifter  
(crack at dog) be examined and dealt with by 2/65 (3ms)

~~C.S. Advanced.~~

It is submitted that this  
vessel is eligible to remain  
as **CLASSED**, subject as now recommended.

18/12/64



© 2021

Lloyd's Register  
Foundation