

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl Se* MERNOO Rpt. *huc* No. 80611

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

P. Long
 Transverse No. 6412 Depth "d" 19.5'
 Framing: Table No. Description *Bull angle frames as approved*
 Longitudinal No. 18476
 Proportions $\frac{\text{Length}}{\text{Depth}} = 12.6 \text{ to U.P.}$
 Deck Sheerstrake *as approved*

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A.1. (Steel).
 1 D* (Stl).
 Cell D B 242' 6045, F.P.T. 975, A.P.T. 1395.
 F.K, H.B.H, Cem, *Ways* A.C.P.
 P 26' B 168' F 29'.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2021

Lloyd's Register Foundation

014827-014834-0015

10.9.26

Are Frame and Reversed Frame joggled?.....

Frame only

Bridge Deck, [.....]

Spacing.....