

M/S LUCIANO CASTRO

Submitted Santos Laveras be informed that, to permit reclassification with record of E.S. 4/64, the following should be examined:-

Main Engine scavenge pump + compressor

Crankcase relief devices

Independent F.W. cooling pump and lub. oil pumps.

Both generator engines.

All machinery should be examined under working conditions.



© 2021
Ed
31/12/64

Lloyd's Register
Foundation

014835-014842-0222