



Lloyd's Register of Shipping.

UNITED WITH THE BRITISH CORPORATION REGISTER

Calle 25 de Mayo 158,

BUENOS AIRES, 29th. May, 1952.-

RECEIVED

- 3 JUN 1952

Ans.....

Dear Sir,

M.V. "AGUILA II"

Further to my letter of the 21st. inst. concerning the overdue donkey boiler survey of this vessel, we enclose herewith the original letter of reply today received from the Owners.

This entirely unsatisfactory reply regarding a minor item of survey would not indicate any intention of the New Owners to submit the vessel to the Periodical Special Survey which becomes due at the end of next month.

Recently I learnt from a local contractor that they have accounts long outstanding for repairs to various vessels of this Owner amounting to nearly a half million pesos and have been unable to obtain any satisfaction.

We await your instructions.

Yours faithfully.

for The Surveyors.

Min Rennie

"The Secretary",
LONDON.-



© 2021

Lloyd's Register
Foundation

014899 - 014911 - 0066

JK?

LIAM-RIA YB

Enquiries to Registrar & Dyol

RECEIVED

821 050M 00 25 01128

- 8201, YEM .dtes SERIA 2000000

RECEIVED

5201 JUL 5

712 1980

"II ALIUDA".V.M

SHIRTS. .fand .tals ent to tetter ym of tetter
ew, lessav and to yevina telled yeked eubrevo the
bevlaser yabot ylqer to tetter lantigro the ntlwera eelwase
from the omers.

8 gubrtger ylqer ytoctstaltanu ylerltne sht
ent to nolltrent yns etablni for bluw yevina to noll tennim
lelceqel laltbolter ent of lessav ent yltmua to noll tennim
dltom tken to bre ent te eub samesed dltw yevy
yent tadt totctrtnos lssol e mott tntrel I yltneceh
suoltav of atltqer tot gubrtststuo grol stnucos evan
nollm lant e yltren of gubrtststuo tennw sht to a lessav
nolltststas yns nltsto of eldenu need evan bre saseq
basas and have been need evan bre saseq

snolltststani twoy flawe ew

yltltntltat stnucy

stoyevttus ent tot

"ytstetere ent"
- .WOTYOL

CLASSIFICATION

© 2021

Lloyd's Register
Foundation