



Lloyd's Register of Shipping,

Calle 25 de Mayo 158,

Buenos Aires, 8th. September 1936.

LLOYD'S REGISTER
RECEIVED
-7 OCT 1936
ASSA.
LONDON

AND ENGINEER SURVEYORS:
G. WILLIAMSON.
MATHESON.
A. EAGLESOME.
AINTITH.

Dear Sir.

S.

In reply to your classing letter of 14th. ult;
regarding Report N° 14523 "AGUILA II", I have to state that
the new electric generator set has replaced the original
paraffin motor set, which has been removed from the vessel.

It is regretted this was not stated on the report.

We are, Dear Sir.

Yours faithfully.

for The Surveyors.

A. Eaglesome

The Secretary.

LONDON.



© 2021

Lloyd's Register
Foundation

014899-014911-0116

Referred to the Chief Engineer Surveyor

RECEIVED
OCT 1 1936
LLOYD'S REGISTER

Lloyd's Register of Shipping

Calle 22 de Mayo 128

Buenos Aires, 8th. September 1936.

© 2021

Lloyd's Register Foundation



Dear Sir,

In reply to your enclosing letter of 14th. ult. I have to state that the new electric generator set for the vessel has been removed and now the vessel is being fitted with a better generator set. The vessel is now being fitted with a better generator set.

We are, Dear Sir,

Yours faithfully,

for the Surveyors

The Secretary

LONDON

Referred to the Chief Engineer Surveyor

- 7 OCT 1936

also for Mr. Spinks to note.

Noted
24/9/100/36

R.S.

W. S. Spinks