

"G. C. Brovig."

Lot 8090

The Cottenbury surveyors report that this vessel on her trial trip damaged the port propeller. The propeller has been repaired but the surveyors recommend that it should be renewed at the owners convenience.

It is submitted that
this vessel is eligible for
THE RECORD.

+ L.M.C. 10.30 Subject
~~to the port propeller being renewed at the~~
~~owners convenience.~~ (B)

"Oil Engines A.S.C.S.A 16cy - $21\frac{5}{8}$ - $39\frac{3}{8}$ "
C-L N.H.P. 724 2D.B. - 180 $\frac{1}{2}$.

The surveyors should forward
particulars of the lubricating oil pumps.

(B) Lloyd's Register
Foundation

014961-014473-0213