

23 JUN

SHIP NAME

"F U S U S"

REPORT

Sng.

No. 10749

Standing Conditions of Class:

Subject to keel butt No.7/8 and shell plate C.5 (p.s.) being specially examined and dealt with as necessary at the next drydocking, also to 5 lengths of chain cable being renewed at the earliest opportunity.

Endorsement of Class (B) (As before or None)

Keys due: SPECIAL SURVEY (B) due 1,55 - postponement until 1,56 approved 4.2.55 provided a satisfactory General Examination is held.

Place of Present Survey: (Afloat and in dry dock)

Docking: General Examination as above:
Damage (cause unknown) involving bottom shell plating (p & s.f.):
Equipment (renewal of 75 fathoms of chain cable as above).

Special Features:

Interim Certificate in order (Yes-No-None)

Items Outstanding: (~~None~~ for S.S. ~~OPXASA~~)

ALL S.S. ITEMS.

Work to be completed by:

Recommendation:

SUBMITTED record of docking 4,55 be assigned, subject to keel butt No.7/8 and shell plate C.5 (p.s.) being specially examined and dealt with as necessary at the next drydocking, without other condition, but further ACTION be DEFERRED for Special Survey.

4,55 Sng. Subject
Without.

ENDORSEMENT OF CLASS (B) (AMENDED).
Shell plates A.3 & 7 (s.s.) indented.
Bottom plating (p & s.f.) indented.

IT IS FURTHER SUBMITTED postponement of the Special Survey until 1,56 merits approval.



© 2021

Lloyd's Register
Foundation

[Handwritten signature]
13-6-55