

THE SURVEYORS

TELEPHONE No. 7227

G.P.O. Box 333



M.

Lloyd's Register of Shipping,

BANK OF QUEENSLAND CHAMBERS,
251 GEORGE STREET,

SYDNEY,
N.S.W.

6th September 1921

RECEIVED

LONDON.

RECEIVED 1. 1921

ANS

The Secretary,

Sir,

I beg to acknowledge the receipt of your cablegram of 5 th September 1921, which decoded reads;
"MARELLA" REPLY IMMEDIATELY BY CABLE TO MY COMMUNICATION OF 5TH JULY PARAGRAPH SIX.

and replied as follows;

"MARELLA" ONLY LOWER TWEEN DECKS INSULATED NO CHILLED".

You will have received our Reports, Sydney Numbers 6974 and 7017 on this Refrigerating Installation from which you will note that the Nos 1 and 2 Lower Tween Decks only are insulated, the Upper Tween Decks remain as original, that is between upper and shelter deck, and there is no provision for chilled meat being carried from beams in this vessel.

I am, Sir,

Your Obedient Servant.

A.C. Heron.



© 2021

Lloyd's Register
Foundation

015004-015019-0072

Report to the Chief Engineer Surveyor.

17 OCT 1921

Also for Mr. S. A. Hill to note.

88



© 2021

Lloyd's Register
Foundation