

FRI. SEP. 2 1921

(Received at London Office

No. 6972

REPORT of SURVEY for REPAIRS, &c.

Writing Report 11. 7 1921 When handed in at Local Office 11. 7 1921. Port of Sydney N.S.W.

Survey held at Sydney, N.S.W. Date, First Survey 16. 6. 21 Last Survey 6. 7 1921.
EX "WAHEHE" (No. of Visits 5) Master Martin

on the Wood, Iron or Steel Trade Marella

TONNAGE:- Built at Hamburg By whom Reichs's Schiffsw When 1914 -
7372 7732 Owners Burns Philps & Co. Ltd Port belonging to London.

DER DK 4912 Owners' Address
3991 (if not already recorded in Appendix to Register Book) Woolwich Dry.

veyed Afloat or in Dry Dock? Both Name of Dock Circular Quay. Destined Voyage Singapore.

B=CellDBorDBa feet; uE&B feet; f feet; }
al capacity tons. FPT tons; APT tons; MT feet tons. }
N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides
e tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing,
ers, and of the inner bottom plating, especially in the boiler space.

st Report, No. Port

odMeal Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the
se of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs
account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes;
d besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the
lacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on
e back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned and expired.	Machinery and Boiler Surveys (including date of N.B., if any).
Syd. 12. 20		

amage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why
ey were declined?

Was a damage report made by anyone else? If so, by whom?

IRS, OR EXAMINATION AS PER RULE, FOR Dry Docking, for Propeller Damage.

This vessel placed in Dry Dock, bottom cleaned

examined and found in good Condition.

Rudder examined and found good.

ARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...	Survey confined to above.							
Removed and Fair'd or Repaired ...								
Fair'd or Repaired in place ...								

NT CONDITION OF THE	Stringers	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels.
g of Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
ays	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
fs	State if Tanks now tested	Scuppers	Boats
& Fastenings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Plating	Ceiling	Hatches	Condition, how ascertained
g of ditto	Cement or Asphalt	Planking of Wood Vessels	(State if wedges removed)
ooks & Crutches	Rudder	Caulking ditto	Sails
s	Steering gear and its connections	Treenails ditto	Equipment letter
se Frames	Windlass	Breasthooks & Stemson ditto	Anchors, No. of
ms	Have Pumps now been examined and found effi-	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
	cient?	Timbers of Frame at openings ditto	„ length size
	Have Sluice Valves now been examined and found	Ditto ditto at other places ditto	„ Rule length size
	efficient?	Stringers, Clamps & Shelves ditto	Hawser & Warps
	Have Watertight Doors now been examined and found	Salting ditto	Standing & Running Rigging
	efficient?	(State if examined.)	

neral Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon
this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of
survey, 1,15,” or “to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c.”

This vessel seen in Dry Dock in good Condition,

Class contemplated.

y Fee (per Section 28) ...£	:	:	Fees applied for,
l Damage or Repair Fee (if any) ...£	2	2	19. 7. 1921.
per Sec. 28)			Received by me,
ing Expenses (if chargeable) ...£	:	:	19.
2/nd Surveyor's Fee (if any) ...£	:	:	

A. C. Heron
Surveyor to Lloyd's Register of Shipping.

Committee's Minute
24 Character Assigned
See Minute
in Report.

FRI. 10 FEB. 1922
TUE. 20 FEB. 1922
FRI. MAY. 19 1922

