

BC

23 MAR 1950

Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

S NAME 'STRATTON CROFT' REPORT Hul. No. 56293

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/42.)

The vessel's class BS* (Coasting Service) is temporarily suspended and a Notation to this effect is inserted in the Register Book.

The HULL Surveyors report (1.50), the vessel placed in dry dock and at the request of the Owners Representative the repairs to indented keel and bottom shell plating effected on account of grounding damage, examined and found satisfactory.

See correspondence, endorsement dated 4.11.49 and memo dated 3.1.50.

IT IS SUBMITTED no further action is necessary pending information as to the vessel's future.

Oil
21.3.50
C.M.H.



Lloyd's Register Foundation

015020-015025-0020